



Photograph taken July 11, 2013



Photograph taken May 30, 2013

1st floor framing from Entry



Photograph taken May 30, 2013

Kitchen framing from Landing 200



Photograph taken May 30, 2013

2nd fl attic framing



Photograph taken May 30, 2013

2nd fl attic framing



Photograph taken June 6, 2013

Foundation at Lobby



Photograph taken June 6, 2013

Foundation



Photograph taken June 6, 2013

Foundation



Photograph taken June 13, 2013

Foundation / Rough plumbing - Slab



Photograph taken June 13, 2013

Rough Plumbing at Slab



Photograph taken June 13, 2013

Foundation



Photograph taken June 13, 2013

Slab with rough plumbing



Photograph taken June 20, 2013

Slab



Photograph taken June 20, 2013

Slab / Rough Plumbing



Photograph taken June 20, 2013

Lower Landing - closet side



Photograph taken June 20, 2013

Lower Landing - Lift side



Photograph taken July 11, 2013

Slab



Photograph taken July 11, 2013

Slab





Photograph taken July 11, 2013

Slab



Photograph taken July 11, 2013

Bathroom 201



Photograph taken July 11, 2013

Bathroom 201



Photograph taken July 11, 2013

Kitchen



Photograph taken July 11, 2013

Rough Plumbing - Basement



Photograph taken July 18, 2013

Slab after pour



Photograph taken July 18, 2013

Slab after pour



Photograph taken July 18, 2013

Slab after pour



Photograph taken July 18, 2013

Lower Landing



Photograph taken May 16, 2013



Photograph taken May 2, 2013

Excavation for addition footing



Photograph taken May 2, 2013

Finish floor elevation marked on existing foundation



Photograph taken May 2, 2013

Typical existing window header after demolition



Photograph taken May 2, 2013

Typical existing window header following demolition



Photograph taken May 9, 2013



Photograph taken May 9, 2013

Existing framing between Kitchen 205 & Landing 200



Photograph taken May 9, 2013

Typical existing window framing below post demo



Photograph taken May 16, 2013

Footing for addition foundation wall



Photograph taken May 16, 2013

Footing for addition foundation wall



Photograph taken May 16, 2013

Footing for addition foundation wall by Entry/Lobby



Photograph taken May 16, 2013

Footing in existing basement



Photograph taken May 16, 2013

Framing at Lift / Landings location




Photograph taken May 16, 2013

Framing at Lift / Landings location



Photograph taken May 16, 2013

Attic framing



Photograph taken May 16, 2013

Attic framing



Photograph taken May 16, 2013

Attic framing



Photograph taken August 22, 2013



Photograph taken August 8, 2013

Parking lot from Oak St side



Photograph taken August 8, 2013

Lower parking lot from Oak St



Photograph taken August 8, 2013

Driveway/Parking lot from Choate Park side



Photograph taken August 8, 2013

Site Stone wall at parking lot



Photograph taken August 8, 2013

Steel chimney frame / Slab



Photograph taken August 8, 2013

Slab from rear corner



Photograph taken August 15, 2013

SIPs installation in progress



Photograph taken August 15, 2013

Heavy Timber/ SIPs installation



Photograph taken August 15, 2013

Heavy Timber framing



Photograph taken August 15, 2013

Heavy Timber framing



Photograph taken August 15, 2013

Stone wall at barn in progress



Photograph taken August 15, 2013

Heavy Timber framing



Photograph taken August 22, 2013

Heavy Timber & SIPs



Photograph taken August 22, 2013

Heavy Timber & SIPs from Barn side



Photograph taken August 22, 2013

Heavy Timber & SIPs



Photograph taken August 22, 2013

Heavy Timber / SIPs / Chimney frame



Photograph taken August 22, 2013

Handicap parking area



Photograph taken September 19, 2013



Photograph taken August 29, 2013

Addition framing in progress from exterior



Photograph taken August 29, 2013

Addition framing in progress from ext.



Photograph taken August 29, 2013

Addition framing in progress



Photograph taken August 29, 2013

Addition framing in progress



Photograph taken August 29, 2013

Binder at driveway



Photograph taken August 29, 2013

Binder at parking lot



Photograph taken September 5, 2013

Lower SIPs installation in progress





Photograph taken September 5, 2013

Wood windows installed at 1st fl



Photograph taken September 12, 2013

Addition from exterior



Photograph taken September 12, 2013

Exterior view of chimney



Photograph taken September 12, 2013

Lobby between existing and addition



Photograph taken September 19, 2013

Addition view from driveway



Photograph taken September 19, 2013

Framing lower landing closet



Photograph taken September 19, 2013

Addition



Photograph taken September 19, 2013

Addition - Electrical closet