



Photograph taken October 17, 2013




Photograph taken September 26, 2013

Detention Basin



Photograph taken September 26, 2013

Curbing at driveway



Photograph taken September 26, 2013

Detention basin



Photograph taken September 26, 2013

Addition framing interior



Photograph taken September 26, 2013

Addition framing



Photograph taken September 26, 2013

Addition framing



Photograph taken October 2, 2013

Framed addition



Photograph taken October 2, 2013

Fireplace installed



Photograph taken October 2, 2013

Hallway wall demo'd



Photograph taken October 2, 2013

Rough sprinkler at addition



Photograph taken October 2, 2013

Sprinkler, HVAC in progress



Photograph taken October 10, 2013

Hallway wall re-framed



Photograph taken October 10, 2013

Air Vapor Barrier installed



Photograph taken October 10, 2013

Building scraped



Photograph taken October 10, 2013

Building scraping



Photograph taken October 10, 2013

Building scraping in progress



Photograph taken October 17, 2013

Air vapor barrier installed, Roof in progress



Photograph taken October 17, 2013

Building scraped, Roof install in progress



Photograph taken October 17, 2013

Duct brackets installed



Photograph taken October 17, 2013

Addition kitchen



Photograph taken October 17, 2013

Beam at lower landing



Photograph taken October 17, 2013

Piping at lower landing closet



Photograph taken October 17, 2013

Ships ladder installed



Photograph taken October 17, 2013

Equipment in basement



Photograph taken October 17, 2013

Light poles installed



Photograph taken October 17, 2013

Windows primed, Siding scraped



Photograph taken October 17, 2013

Louvers, Windows installed at kitchen



Photograph taken October 24, 2013

From driveway existing primed



Photograph taken October 24, 2013

Siding repairs and primed